HEM15 Mount Firmware Upgrade History

V20240510   HEM15 Firmware Upgrade (Upgraded Suggested)
          HC: V230420, RA/DEC V240510
Bug Fix:
- Fixed the bug that caused DEC goto error.

V20230420   Firmware Upgrade (Upgrade Suggested)
          HC: V230420, RA/DEC V230420
Changes:
- Hand Controller now displays HC firmware version
- HC internal instruction modification
Improvement:
- Improvement of EC performance
Bug Fix:
- Small bug for HEM44A

V20230305   Firmware Upgrade
          HC: V230305, RA/DEC V220718
New:
- HEM15 mount added
- Press and hold "?" button when power on the mount, the HC will enter "Language Selection" mode

V20220718   New Firmware Package for both HEM27 and HEM44 mounts
          RA/DEC/Hand Controller V220718
New:
- Firmware package for both HEM27 and HEM44
- New Upgrade Utility V3.21 for all Strain Wave Gear mounts and SkyHunter

V20220610   HEM27 Firmware Upgrade
New:
- Using Upgrade Utility V3.04

V20220510   HEM27 Firmware Upgrade
Improvement:
- Improving GOTO Accuracy
Bug Fix:
- Removed hand controller PEC for HEM27EC mount.

V20220310   HEM27 Firmware Upgrade
Improvement:
- Mount performance improvement, such as autoguiding and PEC.

V20220305   Initial Release of HEM27 mount